



- A - Building structure
- B - Damp control course
- C - Insulation layer
- D - Ventilated cavity
- E - Timber boarding
- F - Standing seam bay/clips

Description:  
 Standing seam roofing, ventilated,  
 valley box gutter roof pitch < 15°

NedZink B.V.  
 Hoofdstraat 1  
 NL 6020 AC Budel  
 www.nedzink.com

Drawing number: EN-DFG08

Date: 21-6-2016

