



- A - Building structure
- B - Damp control course
- C - Insulation layer
- D - Ventilated cavity
- E - Timber boarding
- F - Standing seam bay/clips

Description:
 Standing seam roofing, ventilated,
 valley gutter construction roof pitch > 15°

NedZink B.V.
 Hoofdstraat 1
 NL 6020 AC Budel
 www.nedzink.com

Drawing number: EN-DFG09

Date: 21-6-2016

